Make Your Digital BK Borescope Diesel-Ready for Newest Diesel Engine Applications

Front and Side view analog and digital 3.8mm imagers

BK5500-38-1
BK5500-38-2
BK8000-38-1
BK8000-38-2

Features and Benefits

- 3.8mm imagers get into much tighter spaces than standard 8.5mm or 5.5mm imagers
- Front view and side view versions for new digital BK8000, BK6500 and BK5600 models
- Front and side view imagers also available for earlier analog borescopes, including BK5500(A), BK5500W and BK6000
- Side view has permanently attached mirror
  - nothing to fall off the imager
- Imagers are resistant to all common automotive chemicals
- Two year warranty for added purchase security



BK8000-38-1

CE – DE, ES, FR, IT, GB, NL & JP

Country of origin: China

Snap-on is a trademark, registered in the United States and other countries, of Snap-on Incorporated.
All other trademarks are marks of their respective holders.
©Snap-on Incorporated 2014. All Rights Reserved.
Snap-on, 2801 80th Street, Kenosha, WI 53143 www.snapon.com

BK5500-38-1
BK5500-38-2
BK8000-38-1
BK8000-38-2

Related Items

BK8000-38-5	Protective Pouch
BK8000-38-6	Imager cleaning swabs



Applications

The 3.8mm diameter imagers are especially suited for work on the TDI (turbo direct inject) or Clean diesel engines of Volkswagen®, Audi® and Mercedes-Benz® vehicles

- Diesel injection ports
- Glow plug ports
- Aircraft engine inspection
- Any application requiring an imager head less than 5.5mm

Snap-on is a trademark, registered in the United States and other countries, of Snap-on Incorporated.
All other trademarks are marks of their respective holders.
©Snap-on Incorporated 2014. All Rights Reserved.
Snap-on, 2801 80th Street, Kenosha, WI 53143 www.snapon.com

BK5500-38-1
BK5500-38-2
BK8000-38-1
BK8000-38-2

⚠ WARNING



• Use of diagnostic equipment on a rotating engine poses a risk of flying particles and entanglement
Wear safety goggles (User and Bystander).
Use caution in routing cables.
Flying particles can cause injury
Poorly routed cables and test leads can cause entanglement and injury



• Use of diagnostic equipment can cause electrical shock, fire, and explosion
Use caution and proper procedures when connecting and disconnecting leads.
Diagnostic equipment must be located 18 in. or more above floor level.



• Avoid sparks and other sources of ignition.
Electrical shock, flames and explosion can cause injury



• Improper use can cause hazardous conditions
Read and follow all safety precautions accompanying the product
Unexpected electrical, thermal, or mechanical occurrences can cause injury



Read additional safety warnings on pages W1 to W4 in Catalog 1200

Part #	Description	Borescope Used
BK8000-38-1	Front view digital 3.8mm imager, 36”	BK5600, BK6500, BK8000
BK8000-38-2	Side view digital 3.8mm imager, 36”	BK5600, BK6500, BK8000
BK5500-38-1	Front view analog 3.8mm imager, 36”	BK5500, BK5500W, BK6000
BK5500-38-2	Side view analog 3.8mm imager, 36”	BK5500, BK5500W, BK6000

Snap-on is a trademark, registered in the United States and other countries, of Snap-on Incorporated.
All other trademarks are marks of their respective holders.
©Snap-on Incorporated 2014. All Rights Reserved.
Snap-on, 2801 80th Street, Kenosha, WI 53143 www.snapon.com