



PRODUCT ANNOUNCEMENT: #19205  
DATE: MAY 17, 1999  
CATALOG 400 INSERT AT: PAGE 280

FILE INDEX: 23.2  
CJ139




## CJ139 14mm & 18mm Pulley Installer

Install front crankshaft pulley (harmonic balancer)  
**on 1992 to current GM Northstar engines, V6 &  
4 cylinder engines**

### Applications:

- Cadillac GM Northstar 4.6L
- Oldsmobile Aurora 4.0L
- GM V6 2.8L, 3.1L, 3100, 3.4L
- GM 4 cylinder 1.8L & 2.0L



Installing Harmonic Balancer



#### WARNING



● Puller & installer parts under pressure can break.

Wear safety goggles (user & bystanders).

Do not heat pullers.

Do not overstress pullers. Use larger size.

Be aware of hand positions when using slide hammers.



Read and follow instructions.

Broken parts can cause injury.

<u>+Stock</u> <u>Number</u>	<u>+Description</u>	<u>+List</u> <u>Price</u>	<u>+Price</u> <u>Group</u>	<u>Weight</u> <u>LBS/(KG)</u>
CJ139	Front Crankshaft Pulley Installer	\$44.95	B	1.5/(0.68)

\* \* \* \*

Sales Material: Front Page of this Sheet  
Family Code: 00IA20Q70ACC  
Commodity Code: 8479899060  
Parts Reference: To follow  
Branding/Product: Snap-on  
Branding/Package: Snap-on  
Available for Export: Yes  
Country of Origin: USA  
Warranty Code: ZB  
+Inventory Class: 1  
+Order Point: “ ”  
Field Assembled Sets Affected: None

+ Fields for DSS Data Entry

---