



Ford ICP Sensor Socket

1 1/16", 6-point, 3/8" Sq Dr

*Easily remove/install ICP Sensor on
2002 & 2003 Ford 6.0L, Diesel Truck Engines*



Ford ICP Sensor

- 3/8" Sq Dr allows use of smaller ratchet in tight quarters
- Spring retention holds sensor securely
- Chrome finish for quick cleanup & corrosion resistance
- Flank Drive® Wrenching configuration

Specifications:

Wrench Size: 1-1/16"

Drive Size: 3/8"

Wrench Configuration: Flank Drive®, 6-point

Outer Diameter: 1.43" (36.2mm)

Length: 2.55" (64.8mm)

Finish: Chrome



S6196KR
Ford ICP Sensor Socket

WARNING • Read & follow instructions before use.

<u>+Stock</u>		<u>+List</u>	<u>+Price</u>	<u>Weight</u>
<u>Number</u>	<u>+Description</u>	<u>Price</u>	<u>Group</u>	<u>LBS/(KG)</u>
S6196KR	1-1/16" Ford ICP Sensor Socket	\$29.95	A	0.80/(0.36)

* * * *

Sales Material:	Front Page of this Sheet
Family Code:	00IA21S30A3C
Commodity Code:	8204000000
Parts Reference:	n/a
Branding/Product:	Snap-on
Branding/Package:	Snap-on
Available for Export:	Yes
Country of Origin:	USA
Warranty Code:	01
+Inventory Class:	1
+Order Point:	" "
Field Assembled Sets Affected:	None

+ Fields for DSS Data Entry